REPORT DOCUMENTATION PAGE

Form Approved OMB No. 0704-01-0188

The public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing the burden to Department of Defense, Washington Headquarters Services Directorate for Information Operations and Reports (0704-0188), 1215 Jefferson Davis Highway, Suite 1204, Arlington VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to any negative for failing to complete the appropriate of the provision of information in the data needed, and complete the provision of law, no person shall be

				a currently valid C	MB control n	umber.
PLEASE DO NOT RETURN YOUR FORM TO THE ABOVE ADDRESS. 1. REPORT DATE (DD-MM-YYYY) 2. REPORT TYPE						3. DATES COVERED (From - To)
16 Nov 2006 REPRINT						i '
4. TITLE AND S	UBTITLE				5a. CON	TRACT NUMBER
Reply to comment by M. Bodeau on "Charging of mirror surfaces in space"					5b. GRANT NUMBER	
					5c. PROGRAM ELEMENT NUMBER 61102F	
6. AUTHORS					5d. PROJECT NUMBER	
Lai, Shu T.					5021	
					5e. TASK NUMBER RS	
					5f. WORK UNIT NUMBER A1	
7. PERFORMIN	G ORGANIZATIO	N NAME(S) AN	D ADDRESS(ES)			8. PERFORMING ORGANIZATION
Air Force Decembly I showstown A/CDVT						REPORT NUMBER
Air Force Research Laboratory /VSBXT 29 Randolph Road						AFRL-VS-HA-TR-2006-1142
Hanscom AFB, MA 01731-3010						
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)						10. SPONSOR/MONITOR'S ACRONYM(S) AFRL/VSBXT
						THIRE VODAL
	,					11. SPONSOR/MONITOR'S REPORT NUMBER(S)
12 DISTRIBUTE	ONIAVAR ABILE	TV STATEMENT	.,			
12. DISTRIBUTION/AVAILABILITY STATEMENT Approved for Public Release; distribution unlimited.						
40 011001 5145	UTA DV MOTEO	•				
13. SUPPLEMENTARY NOTES Reprinted from Journal of Geophysical Research, Vol. 111, doi:10.1029/2006JA011878, 2006.						
14. ABSTRACT				,		
mirrors. Sput can cause. T equipped with photoemission	tering will only hese conclusion h conventional n of mirrors ma	cause gradual ns are not in dis solar arrays, ra	degradation to solar contagreement with the contagreement mirrors. The ential charging if the spential charging in the sp	ells, not the summent of M. main point ir	idden step Bodeau. In the Lai	at low rates, will shorten the useful life of pwise degradation that sudden discharges Future Boeing 702 series satellites will be article is emphasized: the low 19th, as other parts of the satellite emit
15. SUBJECT T	FRMS					
Spacecraft charging Space plasma physics						
Differential c		Бри	ice plasifia physics			
16. SECURITY CLASSIFICATION OF: 17. LIMITATION OF 18. NUMBER					19a. NAME OF RESPONSIBLE PERSON	
a. REPORT b. ABSTRACT c. THIS PAGE ABSTRACT		ABSTRACT	OF	Shu T. Lai		
				PAGES	19B. TEL	EPHONE NUMBER (Include area code)
UNCL	UNCL	UNCL	UNL			

Click Here Full Article

Reply to comment by M. Bodeau on "Charging of mirror surfaces in space"

Shu T. Lai¹

Received 27 May 2006; revised 24 August 2006; accepted 30 August 2006; published 16 November 2006.

Citation: Lai, S. T. (2006), Reply to comment by M. Bodeau on "Charging of mirror surfaces in space," J. Geophys. Res., 111, A11219, doi:10.1029/2006JA011878.

- [1] The first comment of *Bodeau* [2006] is about the Boeing ownership or acquisitions of companies and satellites. Since I had no knowledge of the companies or the details of acquisitions, and because this is not a scientific question, I will offer no further comment on this point. I thank M. Bodeau for this information.
- [2] Bodeau [2006] comments at length, presenting supporting laboratory measurements, that sputtering rates are small and concludes that sputtering can not cause a sudden stepwise loss of power on Satellite PAS-7. Indeed, Lai [2005] has explored sputtering as a plausible mechanism and obtained a numerical estimate of the surface removal rate by sputtering. The rate obtained by Lai [2005] is of the order of 10⁻¹¹ cm per month. The conclusion section in the work of Lai [2005] states: "Although the sputtering rate is small, prolonged sputtering would shorten the useful life of the mirrors. Unlike sudden discharges, which may cause damage or stepwise degradation to the solar cells, sputtering causes gradual degradation only to the solar cells." This conclusion of Lai [2005] is not in disagreement with that of Bodeau [2006].
- [3] Bodeau [2006] comments that PAS-7 has no mirror. I thank M. Bodeau for this information. However, the PAS-7 articles posted on 27 and 28 September 2001 on SpaceToday.net (http://www.spacetoday.net/Summary/408) and SpaceDaily (http://www.spacedaily.com/news/panamsat-01b.html), respectively, show a satellite picture with mirrors flanking the solar panels. If PAS-7 does not feature mirrors, I agree that the proposed differential charging mechanism would not apply. For Boeing 702 satellites, see http://www.boeing.com/defense-space/space/bss/factsheets/702/galaxy xi/galaxy xi.html. As a

- consequence of degradation, future 702 satellites will be equipped with conventional solar arrays (see the Sat-Index Web site, available at http://www.sat-index.com/failures/702arrays.html).
- [4] The main point in the work of Lai [2005] is a novel postulate that mirrors of high reflectance emit little or no photoemission. With low photoemission, the mirrors may charge to high negative voltages even in sunlight, when the ambient space plasma is hot enough. Charging of mirrors has never been studied in the laboratory. If the satellite surfaces, including parts of the solar panels, emit abundant photoelectrons in sunlight, they would not charge, or charge to low positive potentials only. If so, differential charging may occur on the satellite more often than previously thought. It may occur not only during eclipse periods, which are indeed short, but also sometimes in sunlight when a critical temperature is exceeded. If PAS-7, or any satellite, does not feature reflectors, the proposed differential charging mechanism would not apply.
- [5] Acknowledgment. Amitava Bhattacharjee thanks Henry Garrett for the assistance in evaluating this paper.

References

Bodeau, M. (2006), Comments on "Charging of mirrors in space" by S. T. Lai, J. Geophys. Res., 111, A11218, doi:10.1029/2006JA011720. Lai, S. T. (2005), Charging of mirrors in space, J. Geophys. Res., 110, A01204, doi:10.1029/2002JA009447.

20070117041

S. T. Lai, Space Vehicles Directorate, Air Force Research Laboratory, 29 Randolph Road, Hanscom Air Force Base, MA 01731-3010, USA. (shu.lai@hanscom.af.mil)

¹Space Vehicles Directorate, Air Force Research Laboratory, Hanscom Air Force Base, Massachusetts, USA.